

Inspection Photos

11/19/2020

Operator: SG INTERESTS I LTD # 77330

Location ID: 429333

Gunnison, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 1: Photo taken from the Location entrance, facing north. Photo shows signage required per Delayed IR Form 4 #401721716 conditions has not been posted, or is not plainly visible.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 429333



Photo 2: Photo taken from the northwest end of the Location, facing northeast. Photos 2-3 provide an overview of the Location from northeast, southeast to south.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 429333




Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 429333



Photo 4: See comments under photo 2.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 429333



Photo 5: Photo taken from the top of the berm along the perimeter of the pad. Photo shows example of cracking/stabilization concerns that can be observed along the entire perimeter of the Location. Cracks were observed to exceed 30 inches in areas. Ongoing stormwater monitoring/management appears insufficient.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 6: Photos taken from the top of the berm along the northern perimeter of the pad. Photo on right from the 6/18/2019 inspection. Side by side comparison shows that cracks observed along berms do not appear to have been repaired; Photo on left shows cracking/stabilization concerns remain evident along the perimeter of the Location. Cracks were observed to exceed 30 inches in areas. Ongoing stormwater monitoring/management appears insufficient.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 429333



Photo 7: See comments under photo. Photo shows 6 foot measuring stick within a crack on top of the berm. Photo shows cracks were observed to exceed 30 inches in depth in some areas.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 8: Continued from photo 7. Photo shows cracks were observed to exceed 30 inches in depth in some areas

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 9: Photo taken from the north end of the Location, facing east. Photo shows areas where soils have not been sufficiently stabilized, and appear to be slipping.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 10: Continued from photo 9. Photo shows areas where soils have not been sufficiently stabilized, and appear to be slipping

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 429333



Photo 11: Photo taken from the berm on the east end of the Location. Photo shows example of cracking/erosion degradation that can be observed along the entire perimeter of the Location.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 429333



Photo 12: Photo taken from cut slopes on the west end of the Location. Operator has implemented hydromulch along cut slopes. BMP showing signs of degradation. Maintenance advised prior to failure of BMP.