

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/23/2020

Document Number:

696202023**FIELD INSPECTION FORM**Loc ID 418697 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		inspection@sginterests.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418693	WELL	PA	07/11/2019	GW	051-06098	VOLK 12-89-21 #1	RI
418697	LOCATION	CL			-	VOLK 12-89-21 #1	RI

**General Comment:**

On 11/19/2020, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at SG Interests' Volk 12-89-21 #1 location in Gunnison County, Colorado.

This inspection is also followup to inspection #696201320, and #696201669 to document compliance with the following corrective actions: 1002.f.(2)C: Install or repair required BMPs in accordance with good engineering practices by 6/11/2020.

It was observed in this inspection that the Location remains out of compliance with 1002.f.(2)C

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	418693	Type:	WELL	API Number:	051-06098	Status:	PA	Insp. Status:	RI
Facility ID:	418697	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					BMPs on cut/fill slopes
Ditches	Fail					

Comment: Previous 2 inspections observed that stormwater and erosion control BMPs on the Location were insufficient, or missing pursuant to 1002.f.(2)C. Operator was required to comply with 1002.f.(2)C by 6/11/2020.

It was observed in this inspection that Location remains out of compliance with 1002.f stormwater rules. BMPs remain missing or insufficient to protect and stabilize the cut and fill slopes of the Location; Erosion degradation evident. Stormwater ditch BMPs on the perimeter of the pad, and the western areas of the Location have not been constructed in accordance with good engineering practices, including a sufficient outlet to allow for sediment laden-free stormwater discharge.

Original CA has not been addressed and remains applicable.

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.(2)C. Conduct revegetation/reseeding activities on the slopes and install erosion controls to stabilize the seeded soil.

Date: 06/11/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202024	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296732</a>