

TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 3SENW
Location ID: 334882



**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 3SENW
Location ID: 334882**



Capacity volume doesn't match font size on label.



Unpainted tank is rusting.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 3SENW
Location ID: 334882**



**Run off from diversion ditch over well pad
is creating deep erosion down hillside.**

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 3SENW
Location ID: 334882**



**Run off from diversion ditch over well pad
is creating deep erosion down hillside.**

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 3SENW
Location ID: 334882**



Check dam at entrance of location needs maintained.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 3SEW
Location ID: 334882**



**Sediment movement and build up in ditch.
Coordinates 39.47074 W108.09431**

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 3SEW
Location ID: 334882**



**Road ditch needs maintained.
Coordinates 39.47075 W108.10118**



Channeling under rip rap in ditch.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-67S96W 3SENW
Location ID: 334882**



**Riling of road shoulder is washing away roadside.
Coordinates 39.46961 W108.09975**