

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2020

Submitted Date:

11/25/2020

Document Number:

701001812

FIELD INSPECTION FORM

Loc ID 304719 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
 Address: 5057 KELLER SPRINGS RD STE 650
 City: ADDISON State: TX Zip: 75001

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273684	WELL	PR	01/06/2005	GW	125-08907	ROSE 41-18	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
	Type	Access	
	comment:	Trail through pasture	
	Corrective Action:		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
	Type	TANK LABELS/PLACARDS	
	Comment:	Metal sign by water tank	
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:	Lease sign by water tank	
	Corrective Action:		Date:
	Type	OTHER	
	Comment:	Lease sign by gate	
	Corrective Action:		Date:
Emergency Contact Number:			
	Comment:	<input style="width: 50%;" type="text"/>	
	Corrective Action:	<input style="width: 50%;" type="text"/>	Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment:	<input style="width: 80%;" type="text"/>	
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type	WELLHEAD	
	Comment:	Metal panels around wellhead	
	Corrective Action:		Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 273684 Type: WELL API Number: 125-08907 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central meter run for \(Odell 44-7, Shay 34-7, Rose 31-18, 41-18\) 1600' NW @ Shay 34-7](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: [Access is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701001826	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5298852