

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/19/2020

Document Number:

696302677**FIELD INSPECTION FORM**Loc ID 431567 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                  | Comment |
|--------------|-------|--|---------|
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------------|-------------|
| 431694      | WELL | SI     | 11/01/2018  | OW         | 123-36738 | Circle Ranch Federal LB07-62HN | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | TANK LABELS/PLACARDS  |       |            |
| Comment:             | 300 BBLs Produced Water Tank missing - Capacity Label, see photos |       |            |
| Corrective Action:   | Comply with Rule 210.d.   | Date: | 12/18/2020 |
| Type                 | WELLHEAD  |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | CONTAINERS  |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | BATTERY   |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | LOCATION    |       |  |
| Comment:           | Barbed Wire |       |  |
| Corrective Action: |             | Date: |  |
| Type               | WELLHEAD    |       |  |
| Comment:           | Panels      |       |  |
| Corrective Action: |             | Date: |  |

|                               |     |       |                 |
|-------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>             |     |       | corrective date |
| Type: Gas Meter Run           | # 3 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Emission Control Device | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Plunger Lift            | # 1 |       |                 |

|                                   |                                  |       |  |
|-----------------------------------|----------------------------------|-------|--|
| Comment:                          |                                  |       |  |
| Corrective Action:                |                                  | Date: |  |
| Type: Horizontal Heated Separator | # 2                              |       |  |
| Comment:                          |                                  |       |  |
| Corrective Action:                |                                  | Date: |  |
| Type: Bradenhead                  | # 1                              |       |  |
| Comment:                          | Appears to be plumbed to surface |       |  |
| Corrective Action:                |                                  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 300 BBLS | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents           | # | Capacity | Type        | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | BV CONCRETE |         | ,      |
| Comment:           |   |          |             |         |        |
| Corrective Action: |   |          |             |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 60 BBLS  |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents  | # | Capacity | Type      | Tank ID | SE GPS                |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 5 | 300 BBLS | STEEL AST |         | 40.643390,-104.074180 |
| Comment:  |   |          |           |         |                       |

|                    |          |                     |                     |
|--------------------|----------|---------------------|---------------------|
| Corrective Action: |          | Date:               |                     |
| <b>Paint</b>       |          |                     |                     |
| Condition          | Adequate |                     |                     |
| Other (Content)    |          |                     |                     |
| Other (Capacity)   |          |                     |                     |
| Other (Type)       |          |                     |                     |
| <b>Berms</b>       |          |                     |                     |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     |
| Comment:           |          |                     |                     |
| Corrective Action: |          |                     | Date:               |
| <b>Venting:</b>    |          |                     |                     |
| Yes/No             |          |                     |                     |
| Comment:           |          |                     |                     |
| Corrective Action: |          |                     | Date:               |
| <b>Flaring:</b>    |          |                     |                     |
| Type               |          |                     |                     |
| Comment:           |          |                     |                     |
| Corrective Action: |          |                     | Date:               |

**Inspected Facilities**Facility ID: 431694 Type: WELL API Number: 123-36738 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI - Last MIT 01.03.2018

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <a href="#">Routine Field Inspection. Produced Water Tank missing Capacity Label</a> | petrie | 11/19/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402536781    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294739">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294739</a> |
| 696302678    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294719">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294719</a> |