

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/19/2020

Document Number:

700701904**FIELD INSPECTION FORM**Loc ID 335453 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Katz, Aaron		aaron.katz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261878	WELL	PR	04/17/2002	GW	045-07992	LANGSTAFF RMV 141-16	PR
261880	WELL	PR	04/18/2002	GW	045-07994	LANGSTAFF RWF 313-16	PR

**General Comment:****COGCC Inspection Report Summary**

On Thursday 11/19/20 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 313-16, at Location # 335453 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking

- No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	RWF 313-16 braden head is open to atmosphere Braden heads have a port for manual gauge monitoring		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	YES		
Comment:	RWF 313-16 braden head is open to atmosphere		
Corrective Action:	No form 4 on file in order to be open to atmosphere Contact area engineer	Date:	12/31/2020

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	261878	Type:	WELL	API Number:	045-07992	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	261880	Type:	WELL	API Number:	045-07994	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms		Berms				
Ditches		Check Dams				
		Ditches				

Comment: • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)  
 BMP's require maintenance which in turn can lead to tracking  
 • No evidence of tracking control BMP's

Corrective Action: maintain BMP's  
 Provide proof of tracking control BMP's

Date: 12/31/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402536789	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294745">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294745</a>
700701908	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294725">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294725</a>