

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2020

Submitted Date:

11/20/2020

Document Number:

689805014**FIELD INSPECTION FORM**
 Loc ID 324612 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Moran, Rick		rick.moran@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Kauffman, KP		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212140	WELL	PR	08/01/2018	OW	057-06033	MCCALLUM UNIT 52	PR

**General Comment:**

Inspector on location with Rick Moran to respond to complaint document number 200449273. Complaint references venting and H2S odor at wellhead. Inspector used FLIR camera to record venting occurring at wellhead. No H2S odor observed by inspectors.

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-825-4822

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Venting observed at wellhead. FLIR video attached.		
Corrective Action:	Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.	Date:	11/20/2020

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 212140	Type: WELL	API Number: 057-06033	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Optical Gas Imaging Survey**Survey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Calm Speed: 10 (mph) Direction From: SW Weather: Clear Temperature: 50 (F)Assisting Staff: Rick Moran Camera #: \_\_\_\_\_☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
15:52	PM	15:52	PM	Wellhead(s)

Comment: Venting observed at wellhead.Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.Date: 11/20/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402537506	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295541">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295541</a>
689805015	FLIR Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295536">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295536</a>
689805016	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295537">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295537</a>