

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/20/2020

Document Number:

697601073**FIELD INSPECTION FORM**Loc ID 333014 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241236	WELL	PR	05/01/2020	OW	123-09024	1415 CORP. UNIT C 2	EI

General Comment:

inspection of well and location only, shared battery is present at nearby well on different location and that nearby well and battery are inspected in a separate report than for this well.

Location				
Lease Road:				
Type	Access			
comment:	access through gravel mining operations			
Corrective Action	Comply with Rule 603.f .			Date: 11/27/2020
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	adequate			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	weeds present in and around pumpjack			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment:	no spills observed at surface around wellhead and pumpjack			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Pump Jack	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	#			
Comment:	electric box			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241236 Type: WELL API Number: 123-09024 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402537266	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295192
697601074	weeds at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295191