

Inspection Photos
Operator: BP America
API: 067-05144
Date: 11/20/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Area is upslope from irrigation alignment, with grasses established in a more sparse and grazed condition than down slope, below irrigation.



Photo 3. View of cobble checks placed within the project area. Checks are filling with sediment and will soon require maintenance.



Photo 4. View of cable debris within the western project area.



Photo 5. View of the reference area comprised of irrigated grass field with grasses such as timothy, tall fescue, orchard grass, and sedges.



Photos 6/7. View of closed gates after entering and leaving location.