

# Inspection Photos

API: 071-06858

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/30/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 11/30/2020

## Inspection Photos



**Photo 1.** Facing southwest along the main road. The culvert shown at red arrow is not maintained causing erosion along the side of the road. Lat/Long:37.15900,-104.81291.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 11/30/2020

## Inspection Photos



**Photo 2.** There is erosion at the culvert outlet at Lat/Long:37.15900,-104.81291.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 11/30/2020

## Inspection Photos



**Photo 3.** Facing southwest along the main road. This culvert is not maintained causing erosion along the side of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 11/30/2020

## Inspection Photos



**Photo 4.** Facing north along the main road near the location. The side of the road has eroded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 11/30/2020

## Inspection Photos



**Photo 5.** Facing north along the main road near the location. The side of the road has eroded. The rock check damns have failed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 11/30/2020

## Inspection Photos



**Photo 6.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 11/30/2020

## Inspection Photos



**Photo 7.** Well sign posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06858 | Date: 11/30/2020