



**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: Adequate  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | DEBRIS  |       |            |
| Comment:           | Dead Weeds.   |       |            |
| Corrective Action: | Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P. Corrective Action Date 12/18/2020. See attached photos #1 through 4. | Date: | 12/18/2020 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

| Type                            |                                   |       | corrective date |
|---------------------------------|-----------------------------------|-------|-----------------|
| Type: Deadman # & Marked        | # 4                               |       |                 |
| Comment:                        |                                   |       |                 |
| Corrective Action:              |                                   | Date: |                 |
| Type: Vertical Heated Separator | # 1                               |       |                 |
| Comment:                        |                                   |       |                 |
| Corrective Action:              |                                   | Date: |                 |
| Type: Bradenhead                | # 1                               |       |                 |
| Comment:                        | Appears to be plumbed to surface. |       |                 |
| Corrective Action:              |                                   | Date: |                 |
| Type: Pump Jack                 | # 1                               |       |                 |
| Comment:                        |                                   |       |                 |
| Corrective Action:              |                                   | Date: |                 |
| Type: Bird Protectors           | # 1                               |       |                 |
| Comment:                        |                                   |       |                 |
| Corrective Action:              |                                   | Date: |                 |

**Tanks and Berms:**

| Contents  | # | Capacity | Type      | Tank ID | SE GPS               |
|-----------|---|----------|-----------|---------|----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST |         | 39.871152,104.225767 |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

| Contents       | # | Capacity | Type                | Tank ID | SE GPS |
|----------------|---|----------|---------------------|---------|--------|
| PRODUCED WATER | 1 | <50 BBLs | CONCRETE SUMP/VAULT |         | ,      |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             | NO    |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 202829 Type: WELL API Number: 001-08234 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Appears to be plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p><a href="#">COGCC Inspection Report Summary</a><br/>                     On Friday November 13, 2020 at approximately 11:30am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Champlin 93 Amoco B1, Smith Energy Company, at API #001-08234 in Adams County Colorado.<br/>                     While there, I observed a Shut in well.<br/>                     During this inspection the following possible compliance issues were observed:<br/>                     Dead Weeds, trash and debris. Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P. Corrective Action Date 12/18/2020. See attached photos #1 through 4.<br/>                     A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/>                     This is a summary of inspection report.</p> | finkenbc | 12/02/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 700900361    | Inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301601">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301601</a> |