

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2020

Submitted Date:

12/02/2020

Document Number:

699303030

**FIELD INSPECTION FORM**

Loc ID 454529 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
BEECHERL, ARTHUR	214-728-1840	Regulatory@verdadoil.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454526	WELL	PR	06/01/2019		123-46594	BOYD 24-1H	PR
454528	WELL	PR	06/01/2019		123-46596	BOYD 24-4H	PR
454980	WELL	XX	05/11/2018		123-46820	HELEN 24-14H	ND
454982	WELL	PR	07/15/2018	OW	123-46822	HELEN 24-3H	PR
454983	WELL	XX	05/11/2018		123-46823	HELEN 24-7H	ND
454984	WELL	XX	05/11/2018		123-46824	HELEN 24-11H	ND
454985	WELL	XX	05/11/2018		123-46825	HELEN 24-18H	ND
454989	WELL	XX	05/11/2018		123-46829	HELEN 24-16H	ND
454990	WELL	PR	07/15/2018	OW	123-46830	HELEN 24-4H	PR
454993	WELL	XX	05/11/2018		123-46833	HELEN 24-9H	ND

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 4		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 15		
Comment:	automation		
Corrective Action:		Date:	
Type: Compressor	# 1		

Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:		card in meter house indicates current calibration	
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:		shares containment with crude tanks		
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	12	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:		Date:				

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Revas, Robbie

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Wells Served By Facilities Above**

**AirsID**

API Number
123-46830
123-46822
123-46596
123-46594

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 454526 Type: WELL API Number: 123-46594 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:

Date:

Facility ID: 454528 Type: WELL API Number: 123-46596 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:

Date:

Facility ID: 454980 Type: WELL API Number: 123-46820 Status: XX Insp. Status: ND

Facility ID: 454982 Type: WELL API Number: 123-46822 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:

Date:

Facility ID: 454983 Type: WELL API Number: 123-46823 Status: XX Insp. Status: ND

Facility ID: 454984 Type: WELL API Number: 123-46824 Status: XX Insp. Status: ND

Facility ID: <u>454985</u>	Type: <u>WELL</u>	API Number: <u>123-46825</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>454989</u>	Type: <u>WELL</u>	API Number: <u>123-46829</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>454990</u>	Type: <u>WELL</u>	API Number: <u>123-46830</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>PR</u>				
Corrective Action: <u> </u>			Date: <u> </u>	
<b><u>BradenHead</u></b>				
Date of Last Brhd Test: <u> </u>		Annual Brhd Completed? <u>#Error</u>		
Last Brhd Test Results	Initial Surf Csg Pressure: <u> </u>	Fluid Type: <u> </u>		
	End Surf Csg Pressure: <u> </u>			
Comment: <u> </u>				
Corrective Action: <u> </u>			Date: <u> </u>	
Facility ID: <u>454993</u>	Type: <u>WELL</u>	API Number: <u>123-46833</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 12/2/2020 at approximately 1015 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Verdad Resources location:</p> <p style="text-align: right;">Arnold 02N-64W-24 at</p> <p>Location #454529 in Weld County Colorado.</p> <p>While there, I observed a Multi well pad and tank battery. At the time of inspection location has 4 wells that are PR and 6 wells that have not been drilled.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	12/02/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303031	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301780">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301780</a>