

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/03/2020

Submitted Date:

12/03/2020

Document Number:

699303062

FIELD INSPECTION FORM
 Loc ID 438862 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

22 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438861	WELL	SI	09/01/2020	OW	123-40167	SUMMIT 34C-32HZ	SI
438863	WELL	PR	05/02/2015	OW	123-40168	SUMMIT 3N-29HZ	PR
438864	WELL	PR	03/01/2019	OW	123-40169	SUMMIT 28C-29HZ	PR
438865	WELL	PR	04/28/2015	OW	123-40170	SUMMIT 14C-32HZ	PR
438866	WELL	PR	04/20/2015	OW	123-40171	SUMMIT 13C-32HZ	PR
438867	WELL	PR	04/20/2015	OW	123-40172	SUMMIT 3C-29HZ	PR
438868	WELL	PR	01/01/2020	OW	123-40173	SUMMIT 4C-29HZ	PR
438869	WELL	PR	04/27/2015	OW	123-40174	SUMMIT 36C-32HZ	PR
438870	WELL	PR	12/01/2019	OW	123-40175	SUMMIT 29N-29HZ	PR
438871	WELL	SI	09/01/2020	OW	123-40176	SUMMIT 13N-32HZ	SI
438872	WELL	PR	04/21/2015	OW	123-40177	SUMMIT 30N-29HZ	PR
438873	WELL	PR	04/27/2015	OW	123-40178	SUMMIT 36N-32HZ	PR
438874	WELL	PR	04/28/2015	OW	123-40179	SUMMIT 35N-32HZ	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 13		
Comment:	automation,electric panel and transformer.		
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 13		
Comment:	all appear to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 438861 Type: WELL API Number: 123-40167 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI since 9-1-2020 Form 42(PR) Doc # 402544746 submitted on 12-2-2020

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 438863 Type: WELL API Number: 123-40168 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 438864 Type: WELL API Number: 123-40169 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 438865 Type: WELL API Number: 123-40170 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #ErrorLast Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438866 Type: WELL API Number: 123-40171 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #ErrorLast Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438867 Type: WELL API Number: 123-40172 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #ErrorLast Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438868 Type: WELL API Number: 123-40173 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #ErrorLast Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 438869	Type: WELL	API Number: 123-40174	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:			Date:	
<u>BradenHead</u>				
Date of Last Brhd Test: _____		Annual Brhd Completed? #Error _____		
Last Brhd Test Results		Initial Surf Csg Pressure: _____	Fluid Type: _____	
		End Surf Csg Pressure: _____		
Comment: _____				
Corrective Action: _____			Date:	
Facility ID: 438870 Type: WELL API Number: 123-40175 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment: PR				
Corrective Action:			Date:	
<u>BradenHead</u>				
Date of Last Brhd Test: _____		Annual Brhd Completed? #Error _____		
Last Brhd Test Results		Initial Surf Csg Pressure: _____	Fluid Type: _____	
		End Surf Csg Pressure: _____		
Comment: _____				
Corrective Action: _____			Date:	
Facility ID: 438871 Type: WELL API Number: 123-40176 Status: SI Insp. Status: SI				
<u>Idle Well</u>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: SI since 9-1-2020 Form 42(PR) Doc # 402421752 submitted on 6-15-2020				
Corrective Action: _____			Date:	
Facility ID: 438872 Type: WELL API Number: 123-40177 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment: PR				
Corrective Action:			Date:	
<u>BradenHead</u>				
Date of Last Brhd Test: _____		Annual Brhd Completed? #Error _____		
Last Brhd Test Results		Initial Surf Csg Pressure: _____	Fluid Type: _____	
		End Surf Csg Pressure: _____		
Comment: _____				
Corrective Action: _____			Date:	

Facility ID:	438873	Type:	WELL	API Number:	123-40178	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: test is over 1 year and needs to be done annually

Corrective Action:

Date:

Facility ID:	438874	Type:	WELL	API Number:	123-40179	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 12/3/2020 at approximately 1540 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location: Summit 4C-32 HZ at Location #438862 in Weld County Colorado. While there, I observed a multi-well wellsite. Follow up inspection per Doc # 699301911. During this inspection the following possible compliance issue has been addressed: 1002..(2).D housekeeping: Stained soil by the Summit 34C-32HZ WH has been cleaned and removed.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	12/03/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699303063	location pics	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302879