



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Bradenhead		# 1		
Comment:	IS PLUMBED TO SURFACE			
Corrective Action:				Date:
Type: Gas Meter Run		# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 256343 Type: WELL API Number: 071-06880 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">THIS IS A FOLLOW UP TO INSPECTION DOC#689901640, CA HAS BEEN ADDRESSED.</a>	beardsit	11/24/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103609	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297991">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297991</a>