



39.85173, -108.9095, 6844.8ft, 159°
12/03/2020 03:53:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Tank & meter building.

Douglas Train Unit 1325 API: 05-103-09448
Inspection: 700404394



39.85171, -108.9091, 6848.9ft, 242°
12/03/2020 03:54:06 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Location with gas leak.

Douglas Train Unit 1325 API: 05-103-09448
Inspection: 700404394



39.8517, -108.90916, 6844.9ft, 325°
12/03/2020 03:55:25 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Gas leak.

Douglas Train Unit 1325 API: 05-103-09448
Inspection: 700404394