

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /24NWSW

Location ID: 324490



Photo #2385 from entrance to location.



Photo #2082 Photo from inspection #699801978 conducted on 10/22/20 inlet culvert #1.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /24NWSW

Location ID: 324490



Photo #2386 inlet culvert #1.



Photo #2085 Photo from inspection #699801978 conducted on 10/22/20 inlet culvert #2.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /24NWSW

Location ID: 324490



Photo #2388 inlet culvert #2.



Photo #2084 Photo from inspection #699801978 conducted on 10/22/20 outlet culvert #1.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /24NWSW

Location ID: 324490



Photo #2387 outlet culvert #1.



Photo #2087 Photo from inspection #699801978 conducted on 10/22/20 outlet culvert #2.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /24NWSW

Location ID: 324490



Photo #2389 outlet culvert #2.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /24NWSW

Location ID: 324490



Approximate locations of culverts.