

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2020

Submitted Date:

12/04/2020

Document Number:

694500255

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10551
 Name of Operator: ANDEAVOR FIELD SERVICES LLC
 Address: 539 S MAIN STREET
 City: FINDLAY State: OH Zip: 45840
Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Schneider, Lindsay		Lindsay.Schneider@tsocorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463345	SPILL OR RELEASE	CL	03/25/2019		-	Duncan B-6 Lateral 276	EI

General Comment:

On 12/3/2020, COGCC Environmental Staff, Kris Neidel inspected the spill path for spill number 463345 and Remediation Project # 12865. This spill occurred on 3/14/2019, Andeavor's Environmental consultant, WSP (Andrew Smith and Evan Mason) were present to manually till the area around remaining impacts (see remediation project doc 402508872 for a description of intended work). Vermillion Creek had approximately 5" of water (flowing) below 4 inches of ice. Due to the ice and water the underlying soils was not able to be tilled and treated as planned. WSP broke the ice off of the water and collected soil samples from below the water. All impacted soils shall be remediated to table 910-1 standards. Required Action: within 30 days of receiving analytical results from lab, they shall be submitted on a Form 27 supplemental. See attached Photos.

Inspected Facilities

Facility ID: 463345 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500256	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5303872