

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2020

Submitted Date:

11/30/2020

Document Number:

688309035**FIELD INSPECTION FORM**Loc ID 317368 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 20275Name of Operator: CORAL PRODUCTION CORPAddress: 1600 STOUT ST STE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wieger, Jim	(303) 623-3573	JIMWIEGER@QWESTOFFICE.NET	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269686	WELL	PR	08/01/2020	OW	121-10711	CHRISTIANSEN B-5	PR

General Comment:[Reinspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	one crude oil tank over topped and covered it's labels (see attached photo). Maintain labels.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 888-441-3007

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:	stuffing box leak (see attached photo)		Date:	01/04/2021
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule.		Date:	
Type: Bradenhead	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	triplex pump in shed		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	same earth berms as 100 bbl produced water tank				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	OTHER		,
Comment:	gunbarrel				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:	This produced water tank is in the crude oil tank berms.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,
Comment:	buried on south side of pit berms				
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:	No berms are present (see attached photo).				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 02/01/2021
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					

Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Earth						Inadequate	
Comment:		Animal holes in produced water tank (3) berms (see attached photo).					
Corrective Action:		Repair or install berms or other secondary containment devices per Rule.					Date: 02/01/2021
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	400 BBLS	STEEL AST		,		
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:		same earth berms as 100 bbls produced water tank					
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	300 BBLS	HEATED STEEL AST		,		
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Earth	Adequate						
Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	300 BBLS	STEEL AST		,		
Comment:		Oil over topped one 300 bbls tank from thief hatch and covered labels. Clean tank and labels and prevent overflows.					
Corrective Action:							Date:
<u>Paint</u>							

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above**AirsID**

API Number
121-10711
121-09411
121-09200

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Location Construction

Location ID: 269686 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: [Interim reclamation was already passed on 4/18/2014.](#)

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities			
Facility ID: 269686	Type: WELL	API Number: 121-10711	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	9/1/2020 production reported to COGCC database. No gas produced. There were 18000 bbl produced water reported in 9/1/2020.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment:

Water from pit is running into 100 bbl fiberglass tank at south end of pit and following a drainage from the pit to the pasture a PVC pipe is running water into the pasture on the other side of the pit fence.

Corrective Action Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402542606	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5299978
688309076	Coral Production Christiansen B-5	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5299962