

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2020

Submitted Date:

12/07/2020

Document Number:

700900390

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
319714 \_\_\_\_\_ Finkenbinder, Chane \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                    | Comment |
|---------------|-------|--------------------------|---------|
| Bill Espinosa |       | billespinosa30@yahoo.com |         |
| INGVE, EDWARD |       | ed@renegadeoilandgas.com |         |
| JB Condill    |       | JBCROG@aol.com           |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 201072      | WELL | PR     | 02/01/2020  | OG         | 001-06475 | FERGUSON 2-25 | PR          |

**General Comment:**

**Location**

Overall Good:

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                                 |                                   |       |                 |
|---------------------------------|-----------------------------------|-------|-----------------|
| <b>Equipment:</b>               |                                   |       | corrective date |
| Type: Bradenhead                | # 1                               |       |                 |
| Comment:                        | Appears to be plumbed to surface. |       |                 |
| Corrective Action:              |                                   | Date: |                 |
| Type: Deadman # & Marked        | # 4                               |       |                 |
| Comment:                        |                                   |       |                 |
| Corrective Action:              |                                   | Date: |                 |
| Type: Bird Protectors           | # 3                               |       |                 |
| Comment:                        |                                   |       |                 |
| Corrective Action:              |                                   | Date: |                 |
| Type: Emission Control Device   | # 2                               |       |                 |
| Comment:                        |                                   |       |                 |
| Corrective Action:              |                                   | Date: |                 |
| Type: Vertical Heated Separator | # 1                               |       |                 |
| Comment:                        |                                   |       |                 |
| Corrective Action:              |                                   | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 300 BBLS | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

|                  |          |
|------------------|----------|
| <b>Paint</b>     |          |
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| <b>Berms</b>       |          |                     |                     |             |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |                       |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
| CRUDE OIL          | 2 | 400 BBLs | STEEL AST |         | 39.847845,-104.274359 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

|                  |            |
|------------------|------------|
| <b>Paint</b>     |            |
| Condition        | Inadequate |
| Other (Content)  |            |
| Other (Capacity) |            |
| Other (Type)     |            |

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| <b>Berms</b>       |          |                     |                     |             |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |    |  |       |
|--------------------|----|--|-------|
| <b>Venting:</b>    |    |  |       |
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

|                    |       |
|--------------------|-------|
| <b>Flaring:</b>    |       |
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 201072 Type: WELL API Number: 001-06475 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Appears to be plumbed to surface.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water                  Lined: NO                  Pit ID:                  Lat:                  Long:

Reference Point: \_\_\_\_\_                  Other: \_\_\_\_\_                  Length: \_\_\_\_\_                  Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: None    Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:                          Oil Accumulation:                          2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

| Comment                            | User     | Date       |
|------------------------------------|----------|------------|
| <a href="#">Routine inspection</a> | finkenbc | 12/07/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 700900391    | Inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5304921">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5304921</a> |