

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/07/2020

Submitted Date:

12/07/2020

Document Number:

696104070

**FIELD INSPECTION FORM**

Loc ID 431674 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

25 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431671	WELL	PR	01/30/2014	OW	123-36723	Dillard 20R-443	PR
431676	WELL	PR	09/01/2019	OW	123-36727	Dillard 20R-303	PR
431677	WELL	PR	09/01/2019	OW	123-36728	Dillard 20M-203	PR

**General Comment:**

This is a WELL / BATTERY inspection.  
Well(s): 3: Producing | PR.  
Battery: Active.

**Location**

<b>Lease Road:</b>			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type CONTAINERS		
	Comment: Methanol, Paraffin Inhibitor, Motor Oil.		
Corrective Action:			Date:
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment: 3: Wellsites.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type IGNITOR/COMBUSTOR		
	Comment: Iron panel.		
Corrective Action:			Date:
	Type SEPARATOR		
	Comment: Surrounded by metal berms.		
Corrective Action:			Date:
	Type PUMP JACK		
	Comment: 2: Wellsites. Iron mesh panel.		
Corrective Action:			Date:
	Type WELLHEAD		

Comment:	3: Wellsites. Iron panel w/ braided wire.		
Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	At Dillard 20R-443 wellsite. Gas lift injection manifold.		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Gas Engines drives pumping units.		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	Controls crude oil tanks VOCs. Pilots: ON.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 10		
Comment:	At wellsites. 3: Paraffin Inhibitor pumps, tanks w/ drip containment. Placarded.  At Battery site. 3: ECD scrubbers. 2: Sound walls. 1: Methanol pump, tanks w/ drip containment. Placarded. 1: Motor oil tank w/ drip containment. Placarded.		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	3: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	

Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Calibration card indicates calibration within last year. Last calibration: 11/04/2020. Meter active w/ production.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:					
					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ crude oil tanks.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	9	400 BBLs	STEEL AST		40.565211,-104.572857
Comment:	Equalizer lines connect crude oil tanks.				
Corrective Action:					
					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ produced H2O tanks.			
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	
	Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 431671 Type: WELL API Number: 123-36723 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: No record of Brhd test within last 12 months. Submit current Brhd test.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 431676 Type: WELL API Number: 123-36727 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: No record of Brhd test within last 12 months. Submit current Brhd test.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 431677 Type: WELL API Number: 123-36728 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: No record of Brhd test within last 12 months. Submit current Brhd test.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 12/07/2020 at approximately 14:42 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: PDC ENERGY INC                      Location Name: Dillard /20M-HZ Pad                      Location ID: 431674                      Well Names:                      Dillard 20M-203, 20R-443, 20R-303.                      API: 05-123-36728, 05-123-36723, 05-123-36727.                      Location County: Weld County, Colorado                      Weather: Mostly clear, dry.</p> <p>While there, I observed:                      Well(s): 3: Producing   PR.                      Battery: Active.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/07/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104071	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305245">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5305245</a>