

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

12/01/2020

Document Number:

688800839

FIELD INSPECTION FORM

 Loc ID 333387 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 74650

Name of Operator: RIM OPERATING INC

Address: 5 INVERNESS DRIVE EAST

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Rector, Mike	720-220-1677	mhr@rimop.com	All Inspections
Heil, John		john.heil@state.co.us	
Elledge, Randy	505-320-4969	relledge@rimop.com	All Inspections
Ortiz, Liz	303-799-9828 Ext 304	lortiz@rimop.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214344	WELL	PR	11/28/1961	GW	067-05743	IGNACIO 33-7 19	EI

General Comment:

On November 19, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Rim Operating Inc. Ignacio 33-7 #19. For the most recent field inspection report of this facility, please refer to document #687905312.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near separator.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Produced water vessel has sign listing capacity and contents. NFPA placard is peeling off of tank.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Post and wire fencing around separator and produced water vessel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		37.070729,-107.648264

Comment: **Fiberglass open topped tank with expanded metal cover.**

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	65 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Adequate

Comment: **Secondary containment is inadequate to contain largest single tank plus sufficient freeboard.**

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).	Date:	<u>02/01/2021</u>
--------------------	---	-------	-------------------

Wells Served By Facilities Above

AirsID

API Number
067-05743

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214344 Type: WELL API Number: 067-05743 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402544021	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301068
688800840	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301067