

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/01/2020

Submitted Date:

12/01/2020

Document Number:

700701953

**FIELD INSPECTION FORM**

Loc ID 311696	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 10447 Name of Operator: URSA OPERATING COMPANY LLC Address: 950 17TH STREET, SUITE 1900 City: DENVER State: CO Zip: 80202				<b>Findings:</b> 23 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289580	WELL	PR	05/20/2014	GW	045-13819	Dixon Fed CA B1	PR
289581	WELL	PR	08/01/2012	GW	045-13818	DIXON FED CA B2	PR
289582	WELL	PR	06/15/2011	GW	045-13817	DIXON FED CA B3	PR
289763	WELL	PR	08/01/2012	GW	045-13869	DIXON FED CA B7	PR
291432	WELL	PR	08/01/2012	GW	045-14373	Dixon Federal B10	PR
291433	WELL	PR	08/01/2012	GW	045-14372	DIXON FED CA B6	PR
291434	WELL	PR	01/17/2012	GW	045-14371	Dixon Federal B4	PR
291435	WELL	PR	01/17/2012	GW	045-14370	Dixon Federal B5	PR
291436	WELL	PR	01/17/2012	GW	045-14369	Dixon Federal B9	PR
291437	WELL	PR	09/15/2009	GW	045-14368	DIXON FEDERAL B8	PR
421653	WELL	PR	11/15/2011	GW	045-20424	DIXON FED CA B13	PR
421696	WELL	PR	12/20/2011	GW	045-20425	Dixon Federal B16	PR
421708	WELL	PR	04/20/2012	GW	045-20427	DIXON FED CA B14	PR
421709	WELL	PR	11/01/2012	GW	045-20428	Dixon Federal B11	PR
421710	WELL	PR	09/01/2012	GW	045-20429	Dixon Federal B15	PR
421716	WELL	PR	12/19/2011	GW	045-20432	Dixon Federal B12	PR

**General Comment:**

COGCC Inspection Report Summary

On Friday 12/1/20 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at URSA Dixon A, at Location # 311696 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance
- Lack of stabilization on cut slopes
- No evidence of tracking control BMP's
- Dead man not marked

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Deadman # & Marked	# 9		corrective date
Comment:	one (1) deadman is unmarked		

Corrective Action:	mark or remove deadman		Date:	01/05/2021
Type: Ancillary equipment	# 2			
Comment:	chemical tanks at well heads			
Corrective Action:			Date:	
Type: Bird Protectors	# 10			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 15			
Comment:	All meters have been calibrated on location within the past year.			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 16			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 15			
Comment:	Braden heads have telemetry for monitoring.			
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 15			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:	one (1) tank is heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities						
Facility ID:	289580	Type:	WELL	API Number: 045-13819	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	289581	Type:	WELL	API Number: 045-13818	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	289582	Type:	WELL	API Number: 045-13817	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	289763	Type:	WELL	API Number: 045-13869	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291432	Type:	WELL	API Number: 045-14373	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
Facility ID:	291433	Type:	WELL	API Number: 045-14372	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291434	Type:	WELL	API Number: 045-14371	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291435	Type:	WELL	API Number: 045-14370	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	producing					
Corrective Action:						Date:

Facility ID:	291436	Type:	WELL	API Number:	045-14369	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291437	Type:	WELL	API Number:	045-14368	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	421653	Type:	WELL	API Number:	045-20424	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	421696	Type:	WELL	API Number:	045-20425	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	421708	Type:	WELL	API Number:	045-20427	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	421709	Type:	WELL	API Number:	045-20428	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	421710	Type:	WELL	API Number:	045-20429	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	421716	Type:	WELL	API Number:	045-20432	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

--

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment: <div></div>	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
		Waddles				
Ditches		Ditches				
		Rip Rap				

Comment: 

- Location shows signs of lack of stabilization BMP's in some areas (cut slope, rutting is present) BMP's require maintenance
- Lack of stabilization on cut slopes
- No evidence of tracking control BMP's

Corrective Action: **Maintain BMP's**  
**Provide proof of tracking control BMP's**

Date: 01/05/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402544104	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301167">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301167</a>
700701961	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301162">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301162</a>