

Inspection Photos
Location Name: Conley 6 pad
API #: 007-06208



Old operator sign on ground in weeds, not visible by tanks

Inspection Photos
Location Name: Ignacio Conley 6 pad
API #: 007-06208



Unused and unmarked flowline riser



Unused and unmarked flowline riser



Inspection Photos
Location Name: Conley 6 pad
API # : 007-06208



Unused and unmarked flowline riser



Inspection Photos
Location Name: Ignacio Conley 6 pad
API #: 007-06208



Mineral crust in flat area indicative of produced water release



Exhaust leak

Inspection Photos
Location Name: Ignacio Conley 6 pad
API #: 007-06208



Unused concrete barriers and weeds



Most of rig anchor markers are down or inadequate

Inspection Photos
Location Name: Ignacio Conley 6 pad
API #: 007-06208



Unused equipment northeast side of location



Landowner equipment

Inspection Photos
Location Name: Ignacio Conley 6 pad
API #: 007-06208



Landowner activities and storage on defined/delineated location



Most of rig anchor markers are down or inadequate

Inspection Photos
Location Name: Ignacio Conley 6 pad
API #: 007-06208



Looking east, rill erosion on bermed slope on east side of location



Dead dry weeds encroaching containment

Inspection Photos
Location Name: Ignacio Conley 6 pad
API #: 007-06208



Thief hatches open 12/2/20



Thief hatches open 12/7/20