

Inspection Photos

12/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 324315

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315




Photo 1: 2019 COGIS Aerial image. Photo shows overview of the Location. Photo shows Location does not comply with Rule 1003.b.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 2: Photo taken from the southeast end of the Location, facing west. Photos 1-2 provide an overview of the Location from west to north. Photo also shows areas not reasonably needed for production on the Location have not been reclaimed in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 4: Photo taken from the southeast end of the Location, facing north. Photo shows BMPs to stabilize the cut slopes of the Location are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 5: Photo taken from the east end of the Location, facing northeast. Photo shows BMPs to stabilize the cut slopes of the Location are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 6: Photo taken from the south end of the Location, facing south. Photo shows BMPs to stabilize/protect the fill slopes, and prevent off-site sediment transport are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 7: Photo taken from the south end of the Location, facing southwest. See comments under photo 6.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 8: Photo taken from the west end of the Location, facing northwest. See comments under photo 6.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 9: Photo taken from the southwest corner of the Location, facing north. Photos 9-11 provide an overview of the Location from north, northeast to east. Photos show areas not reasonably needed for production on the Location have not been reclaimed in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 10: See comments under photo 9.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 11: See comments under photo 9.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 12: Photo taken from the northwest corner of the Location, facing north. Photos 12-14 provide an overview of the Location from east, southeast to south. Photos show areas not reasonably needed for production on the Location have not been reclaimed in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 13: See comments under photo 12.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 14: See comments under photo 12.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 324315



Photo 15: Photo of well on Location.

