

Inspection Photos

API: 017-06899

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 12/8/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-06899 | Date: 12/8/2020

Inspection Photos



Photo 1. Facing north toward the access road. The road has been reclaimed and temporarily stabilized with straw mulch. It appears livestock have been utilizing the area near the fenceline and reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06899 | Date: 12/8/2020

Inspection Photos



Photo 2. Facing west toward the location standing from a distance. The location is fenced and appears to be reclaimed and straw mulch applied.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06899 | Date: 12/8/2020