

Inspection Photos
Operator: BP America
API: 067-07003
Date: 12/7/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area facing northward. Cars identified within the project area during a previous reclamation inspection, are moved off of the project area.



Photo 3. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, intermediate wheatgrass, and sand dropseed, as well as weeds such as cheatgrass. As jointed goatgrass was identified during previous inspections, spring monitoring and treatment will likely be needed.



Photo 4 View of the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of squirreltail, blue grama, and penstemon spp.