

Inspection Photos

12/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335902

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 5: Photo taken from the east end of the Location, facing east. Photo shows trash debris (orange barrel) on the slopes east of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 6: Photo taken from the northeast corner of the Location, facing northeast. Photo shows BMPs at the soil stockpile are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 7: Photo taken from the northeast end of the Location, facing south. Photos 7-9 provide an overview of the Location from south, southwest, to west. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 8: See comments under photo 7.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 9: See comments under photo 7.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 10: Photo taken from the west end of the Location, facing south. Photos 10-12 provide an overview of the Location from northeast, east to southeast. Photos also show areas not reasonably needed for production on the Location have not been reclaimed. Photos also show cuttings on Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 11: See comments under photo 10.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 12: See comments under photo 110.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 13: Photo taken from the soil stockpile on the west end of the Location. Vegetation observed on soil stockpile predominantly undesirable weedy plant species such as cheatgrass; This does not comport with Rule 1002.c.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 14: Photo taken from the southwest end of the Location, facing south. Photo shows BMPs at the soil stockpile are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 15: Photo taken from the southwest end of the Location, facing north. Photo shows BMPs at the soil stockpile are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 16: Photo taken from east end of the Location, facing south. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 17: Photo shows active wells on the Location.

