

Inspection Photos

12/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335902

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



20201208

Photo 1: Photo taken from the south end of the Location, facing west. Photos 1-3 provide an overview of the Location from west, north, to east. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 4: Photo taken from the southwest corner of the Location, facing southwest. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 5: Photo taken from the west end of the Location, facing north. Photos 5-8 provide an overview of the Location from north, northeast, southeast to south. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 7: See comments under photo 5.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 8: See comments under photo 5.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 9: Photo taken from the northwest corner of the Location, facing northwest. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 10: Photo taken from the north end of the Location, facing east. Photos 10-13 provide an overview of the Location from east, southeast, southwest to west. Photos also show areas not reasonably needed for production on the Location have not been reclaimed. Photos also show cuttings on Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 11: See comments under photo 10.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 12: See comments under photo 10.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 13: See comments under photo 10.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 14: Photo taken from the east end of the Location, facing south. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 15: Photo taken from the east end of the Location, facing south. Photos 15-18 provide an overview of the Location from south, southwest, northwest to north. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 16: See comments under photo 15.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 17: See comments under photo 15.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



20201208

Photo 18: See comments under photo 15.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335902



Photo 19: Photo taken from the access road, facing northeast. Photo shows BMPs to stabilize/protect slopes of access road are missing, or insufficient. Slopes predominantly bare/exposed soils, revegetation activities required.