

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2020

Submitted Date:

12/11/2020

Document Number:

688000495**FIELD INSPECTION FORM**Loc ID 401528 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 55575Name of Operator: MCELVAIN ENERGY INCAddress: 511 16TH STREET SUITE 700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hulstrom, Michelle	(303) 893-0933 X381	michelleh@mcelvain.com	
Caplis, Chris		chris.caplis@mcelvain.com	
Wilson, Amy	3036-893-0933 x315	amy.wilson@mcelvain.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
102680	PIT				-	SHEIBLEY 1	EI
102681	PIT				-	SHEIBLEY 1	EI

**General Comment:**

Environmental inspection related to Rem #1519. Former landfarm oily soil requires removal and proper disposal. Contact NE EPS Rob Young ([rob.young@state.co.us](mailto:rob.young@state.co.us)) with any questions.

Inspected Facilities				
Facility ID: 102680	Type: PIT	API Number: -	Status:	Insp. Status: EI
Facility ID: 102681	Type: PIT	API Number: -	Status:	Insp. Status: EI

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Environmental inspection related to Rem #1519.

Corrective Action: Remove and properly dispose of remnant oily soils. Prepare former landfarm area for adequate reclamation per Rule 1004.

Date: 01/15/2021

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000496	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308607">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308607</a>
688000497	Letter from COGCC to McElvain 4/10/2003	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308608">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308608</a>