

Inspection Photos

12/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335815

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 1: Google Earth aerial imagery. Photo shows areas not reasonably needed for production on the south, southeast north, northwest and western areas of the Location have not been reclaimed. Red circles represent a 75 foot buffer around the drilled wells on the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 2: Photo taken from the northeast end of the Location, facing south. Photos 2-4 provide an overview of the Location from south, southwest to west. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 4: See comments under photo 2.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 5: Photo taken from the east end of the Location, facing south. Photos 5-8 provide an overview of the Location from south, southwest northwest to north. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 7: See comments under photo 5.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 8: See comments under photo 5.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 9: Photo taken from the east end of the Location, facing north. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 10: Photo taken from the east end of the Location, facing east. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient. Photo also shows concrete debris on the slope; this is considered trash debris and requires removal.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 11: Photo taken from the southeast end of the Location, facing southeast. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 12: Photo taken from the west end of the Location. Photo shows pipe debris remaining on the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 13: Photo taken from the southeast end of the Location, facing northeast. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient. Photo also shows plastic trash debris on slopes.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 14: Photo taken from the south end of the Location, facing west. Photos 14-16 provide an overview of the Location from west, northwest to north. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 15: See comments under photo 14.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 16: See comments under photo 14.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 17: Photo taken from the cut slopes on the south end of the Location, facing west. Photo shows BMPs remain missing or insufficient to stabilize and protect slopes.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815




Photo 18: Photo taken from the southwest end of the Location, facing north. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 19: Photo taken from the north end of the Location, facing east. Photos 19-23 provide an overview of the Location from east, southeast, southwest, west to northwest. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 20: See comments under photo 19.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 21: See comments under photo 19.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 22: See comments under photo 19.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 23: See comments under photo 19.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 24: Photo taken from the north end of the Location, facing southeast. Photo shows ditch on the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 25: Continued from photo 24. Photo taken from the north end of the Location, facing west. Photo shows ditch on the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 26: Continued from photo 24. Photo shows ditch outlet. Photo shows BMPs have not been constructed in accordance with good engineering practices; BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 27: Photo taken from the northwest end of the Location, facing southeast. Photo shows trash debris observed on the slopes.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 28: Photo taken from the west end of the Location, facing east. Photo shows producing wells on the north end of the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335815



Photo 29: Photo taken from the southern end of the Location, facing south. Photo shows the 1 producing well on the south end of the Location.