

**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**GV 22-29 well has gas bubbling up from around casing.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**GV 22-29 well has gas bubbling up from around casing.**



**GV 22-29 well has gas bubbling up from around casing.**





**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Subsidence at separators.**

**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Rutting on location.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**PVC pipe over the edge of location.**



**Rutting on location**

**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Riling running off road running through location.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Equipment and materials on location not needed for production of wells.**



**Pipe stored in location drainage ditch.**

**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Pipe over the edge of location. South end of location.**



**Tread protectors and junk over the edge of location. South end of location.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Pieces of culvert off the edge of location.  
East side along roadway.**

**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Rutting on location.**



**Ruts on roadway and in ditch.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Unmaintained waddles south of location  
on west side of road.**



**Unmaintained straw bales running along  
east edge of location.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Unused equipment south east of location  
at frac lines.**



**Unused 2" ball valve.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Unmaintained straw bales running along  
east edge of location.**



**Unmaintained straw bales running along  
east edge of location.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Unmaintained waddles and straw bales  
running along east edge of location.**



**Unmaintained waddles and straw bales  
running along east edge of location.**



**TEP ROCKY MOUNTAIN LLC**  
**ARCO-66S96W 29NESE**  
**Location ID: 335184**



**Unmaintained waddles and straw bales  
running along east edge of location.**