

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2020

Submitted Date:

12/11/2020

Document Number:

701100879

FIELD INSPECTION FORM

Loc ID 335184 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210864	WELL	PR	04/19/1990	GW	045-06622	ARCO GV 22-29	PR
288039	WELL	PR	07/25/2007	GW	045-13155	PUCKETT GM 434-29	PR
288040	WELL	PR	07/25/2007	GW	045-13154	PUCKETT GM 323-29	PR
288041	WELL	PR	07/25/2007	GW	045-13153	PUCKETT GM 343-29	PR
288042	WELL	PR	07/25/2007	GW	045-13152	PUCKETT GM 444-29	PR
288043	WELL	PR	07/25/2007	GW	045-13151	PUCKETT GM 443-29	PR
288044	WELL	PR	07/25/2007	GW	045-13150	PUCKETT GM 543-29	PR
288045	WELL	PR	07/25/2007	GW	045-13149	PUCKETT GM 333-29	PR
288046	WELL	PR	06/29/2008	GW	045-13148	PUCKETT GM 534-29	PR
288047	WELL	PR	07/25/2007	GW	045-13147	PUCKETT GM 33-29	PR
288048	WELL	PR	07/31/2008	GW	045-13146	PUCKETT GM 634-29	PR
288049	WELL	PR	07/25/2007	GW	045-13145	PUCKETT GM 423-29	PR
288050	WELL	PR	07/25/2007	GW	045-13144	PUCKETT GM 334-29	PR
288051	WELL	PR	07/12/2008	GW	045-13143	PUCKETT GM 34-29	PR

General Comment:

COGCC Inspection Report Summary

I, Inspector Mike Longworth, conducted an inspection at TEP ROCKY MOUNTAIN LLC, ARCO-66S96W 29NESE, Location ID: 335184 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

GV 22-29 well has gas leaking up from around casing. 24 hours to fix the leak or isolate leak.

Equipment and materials on location not needed for production of wells. Pipe stored in location drainage ditch.

Pipe over the edge of location at south end of location. PVC pipe over the edge of east side of location. Pieces of culvert off the edge of location. Unused 2" ball valve at frac lines south of location. Tread protectors and junk over the edge of location at south end of location.

Rutting on location. Ruts on roadway and in ditch. Subsidence at separators. Riling running off road running through

location. Unmaintained straw bales running along east edge of location. Unmaintained waddles south of location on west side of road.

I spoke with Brad Moss with TEP about the gas leaking at GV 22-29 by phone 1030am 12/11/2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	TRASH		
Comment:	Pipe over the edge of location at south end of location. PVC pipe over the edge of east side of location. Pieces of culvert off the edge of location. Unused 2" ball valve at frac lines south of location. Tread protectors and junk over the edge of location at south end of location.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/28/2020
Type	STORAGE OF SUPL		
Comment:	Equipment and materials on location not needed for production of wells. Pipe stored in location drainage ditch.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/12/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210864	Type:	WELL	API Number:	045-06622	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	GV 22-29 well has gas leaking up from around casing.								
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.					Date:	12/12/2020		
Facility ID:	288039	Type:	WELL	API Number:	045-13155	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288040	Type:	WELL	API Number:	045-13154	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288041	Type:	WELL	API Number:	045-13153	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288042	Type:	WELL	API Number:	045-13152	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288043	Type:	WELL	API Number:	045-13151	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288044	Type:	WELL	API Number:	045-13150	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288045	Type:	WELL	API Number:	045-13149	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								

Corrective Action:		Date:	
Facility ID: <u>288046</u> Type: <u>WELL</u> API Number: <u>045-13148</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<u>Producing Well</u>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>288047</u> Type: <u>WELL</u> API Number: <u>045-13147</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<u>Producing Well</u>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>288048</u> Type: <u>WELL</u> API Number: <u>045-13146</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<u>Producing Well</u>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>288049</u> Type: <u>WELL</u> API Number: <u>045-13145</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<u>Producing Well</u>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>288050</u> Type: <u>WELL</u> API Number: <u>045-13144</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<u>Producing Well</u>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>288051</u> Type: <u>WELL</u> API Number: <u>045-13143</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<u>Producing Well</u>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Rutting on location. Ruts on roadway and in ditch. Subsidence at separators. Riling running off road running through location. Unmaintained straw bales running along east edge of location. Unmaintained waddles south of location on west side of road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/28/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701100880	Inspection 701100879 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308646