

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-1-69S98W /1SWNE

Location ID: 312658



Photo #2455 from entrance to location.



Photo #2456 Debris inside tank containment.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-1-69S98W /1SWNE

Location ID: 312658



Photo #2457 Sediment migrating off of location and into access road ditch.



Photo #2458 Rill erosion occurring on SE side of location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-1-69S98W /1SWNE

Location ID: 312658



Photo #2459 Rill erosion occurring on SE side of location.