

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2020

Submitted Date:

12/11/2020

Document Number:

699802242

**FIELD INSPECTION FORM**

Loc ID 312658 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, BLM		jbyers@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
Graves, Jim		mrinc20@maralexinc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222099	WELL	PR	09/09/1997	GW	077-08701	SULFUR GULCH 9-98-1 1	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Friday 12/11/20 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at MARALEX RESOURCES INC SULFUR GULCH 9-98-1-69S98W /1SWNE, Location #312658 in Mesa County Colorado.  
While there, I observed normal production operations.  
During this inspection the following possible compliance issues were observed: Debris inside tank containment. See photo #2456 with a corrective action date of 12/25/20. Sediment migrating off of location and into access road ditch. Rill erosion occurring on SE side of location. See photo #2457, #2458, and #2489 with a corrective action date of 12/26/20.  
  
A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris inside tank containment. See photo #2456		
Corrective Action:	Production facilities, shall be kept free of debrs. Remove all debris from location.		Date: 12/25/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:			Date:
Type:	Plunger Lift	# 1	
Comment:			
Corrective Action:			Date:
Type:	Bird Protectors	# 1	
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head Valves are accessible.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 222099 Type: WELL API Number: 077-08701 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Compaction				
		Ditches				
Berms						
		Berms				
		Culverts				
Other						Sediment migrating off of location
Compaction						
		Gravel				

Comment: Sediment migrating off of location and into access road ditch. Rill erosion occurring on SE side of location. See photo #2457, #2458, and #2489

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 12/26/2020

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802243	Photos for Insp. #699802242	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308770">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308770</a>