

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2020

Submitted Date:

12/13/2020

Document Number:

696104102

FIELD INSPECTION FORM

Loc ID 302874 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285136	WELL	SI	12/01/2018	OW	123-29961	PAPPENHEIM 34-26	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / CEMENTING** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations / Cementing. Final plug.
Battery: Inactive | Shut-down.
Inactive Battery SE corner GPS coordinates: 40.541980 / -104.507874

Reference Field Inspection Report doc. #696104039 dated 12/01/2020.
Had Corrective Action for:
Emergency number NOT posted at wellsite.
Company and/or well name NOT posted at wellsite. Refer to Rule 210.b.
Corrective Action is cleared due to well being **PLUGGED & ABANDONED** | PA.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Workover jobsite safety signage present.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Prior insp: Emergency number NOT posted at wellsite. Company and/or well name NOT posted at wellsite. Refer to Rule 210.b. Post valid Emergency number, Company, & well name at wellsite. Comply w/ Rule 210.b. Corrective Action date: 03/01/2021. This insp: Reference Field Inspection Report doc. #696104039 dated 12/01/2020. Had Corrective Action for: Emergency number NOT posted at wellsite. Company and/or well name NOT posted at wellsite. Refer to Rule 210.b. **Corrective Action is cleared due to well being PLUGGED & ABANDONED PA. See photos #1-3.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696104037 and/or Location ID #305809 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	See comment in Signs/Marker section for Wellhead.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696104037 and/or Location ID #305809 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Equipment:			
Type: Emission Control Device	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment assigned to Location ID #305809.		

Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Plugged & Abandoned PA. Equipment assigned to Location ID #305809.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Plugged & Abandoned PA. Equipment assigned to Location ID #305809.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Plugged & Abandoned PA. Equipment assigned to Location ID #305809.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Plugged & Abandoned PA. Equipment assigned to Location ID #305809.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
--------	--	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 285136 Type: WELL API Number: 123-29961 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Duco Cementers Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 680' - 0' Cement Volume (sx): 204 sxs

Good Return During Job: YES Cement Type: Class "G-Neat" 15.8#

Comment: [Workover Contractor: Ensign. Rig #351.](#)
[Cementing Contractor: Duco Cementers.](#)

Reference:
[Form 42 doc. #402550421 indicates notice of plugging start date: 12/10/2020. Approved.](#)
[Form 6 doc. #402533645 Notice of intent to Abandon date: 11/19/2020. Approved.](#)

Final Plug:
 RIH WITH MULE SHOE 22JNTS 2 3/8 TUBING DOWN TO 680' R/U PUMP BREAK CIRCULATION WITH 5BBL CONDITIONED ANNULUS FOR 35MIN, R/D PUMP. MIRU DUCO CEMENTERS, HELD SAFETY MEETING. ESTABLISHED CIRCULATION WITH 5BBL FRESH WATER AHEAD, MIXED/PUMPED 204SXS (41.3.4BBL) G-NEAT 15.8# CEMENT FROM 680-SURF RETURNED 2BBL CEMENT TO SURFACE MAINTAINED GOOD CIRCULATION THROUGHOUT JOB. R/D CEMENTERS L/D 22JNTS TO TRAILER. R/D WASH UP CEMENTERS. R/D WORK FLOOR TUBING EQUIPMENT N/D BOP SWI CREW CLEANED LOCATION INSTALLED WELL FENCE MOVED RIG/EQUIPMENT TO SIDE OF LOCATION.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 12/11/2020 at approximately 14:57 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: PAPPENHEIM-67N64W /26SWSE Location ID: 302874 Well Name: Pappenheim 34-26 API: 05-123-29961 Location County: Weld County, Colorado Weather: Overcast, wet from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations / Cementing. Final plug. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.541980 / -104.507874</p> <p>Reference Field Inspection Report doc. #696104039 dated 12/01/2020. Had Corrective Action for: Emergency number NOT posted at wellsite. Company and/or well name NOT posted at wellsite. Refer to Rule 210.b. **Corrective Action is cleared due to well being PLUGGED & ABANDONED PA. See photos #1-3.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/11/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104103	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5309117