

Inspection Photos
Operator: Logos Operating
API: 067-08122
Date: 12/9/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern reclamation area from the northeastern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass, and others in a grazed vegetative condition.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the reference area comprised of mixed sagebrush shrubland and pinyon/juniper woodland with grasses such as western wheatgrass and blue grama in the understory. Forbs were not observable at this time.