

Inspection Photos
Operator: Simcoe
API: 067-08831
Date: 12/9/2020



Photo 1. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass, intermediate wheatgrass, and sand dropseed.



Photo 2. View of the northern reclamation area from the northeastern corner facing westward.



Photo 3. View of the reference area comprised of mixed sagebrush shrubland and pinyon/juniper woodland with grasses such as western wheatgrass and blue grama in the understory. Forbs were not observable at this time.