

Inspection Photos
Operator: Logos Operating
API: 067-08297
Date: 12/9/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern reclamation area from the northwestern corner facing eastward. Revegetation is progressing with grasses such as western wheatgrass, intermediate wheatgrass, and sand dropseed, largely in a grazed vegetative condition.



Photo 3. View of the southern reclamation area from the southeastern corner facing westward.



Photo 4. View of the reference area comprised of mixed sagebrush shrubland and pinyon/juniper woodland with grasses such as western wheatgrass and blue grama in the understory. Forbs were not observable at this time.