

Inspection Photos
Operator: Logos Operating
API: 067-08121
Date: 12/9/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the fill slope from the northeastern corner facing westward. Revegetation is progressing with grasses and shrubs such as western wheatgrass and rubber rabbitbrush.



Photo 3. View of the eastern reclamation area from the northeastern corner facing southward.



Photo 4. View of the reference area comprised of mixed sagebrush shrubland and pinyon/juniper woodland with grasses such as western wheatgrass and blue grama in the understory. Forbs were not observable at this time.