

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2020

Submitted Date:

12/14/2020

Document Number:

700702022

FIELD INSPECTION FORM

 Loc ID 335386 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10531
 Name of Operator: GRIZZLY OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276751	WELL	PR	04/02/2008	GW	045-10521	FERGUSON 34B-27-692	PR
276753	WELL	PR	10/10/2005	GW	045-10522	FERGUSON 44D-27-692	PR
276756	WELL	PR	06/01/2013	GW	045-10523	FERGUSON 44B-27-692	PR
276759	WELL	PR	04/02/2008	GW	045-10524	FERGUSON 34D-27-692	PR

General Comment:

COGCC Inspection Report Summary

On Monday 12/14/20 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Ferguson, at Location # 335386 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. Limited storm water inspection due to snow.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking
- No evidence of tracking control BMP's
- Berm next to combustor needs maintenance

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text" value="911"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:		corrective date
Type: Gas Meter Run	# 4	
Comment:	All meters have been calibrated on location within the past year.	
Corrective Action:		Date:
Type: Bird Protectors	# 6	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 4	
Comment:	Braden heads have a port for manual gauge monitoring	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	Ignitor/Combustor
------	-------------------

Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>276751</u>	Type:	<u>WELL</u>	API Number:	<u>045-10521</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>276753</u>	Type:	<u>WELL</u>	API Number:	<u>045-10522</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>276756</u>	Type:	<u>WELL</u>	API Number:	<u>045-10523</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>276759</u>	Type:	<u>WELL</u>	API Number:	<u>045-10524</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail	Ditches				

Comment: Limited storm water inspection due to snow.
 • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance which in turn can lead to tracking
 • No evidence of tracking control BMP's
 • Berm next to combustor needs maintenance

Corrective Action: maintain ALL BMP's
 Provide proof of tracking control BMP's

Date: 01/14/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702025	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310061