

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead Weeds,(next to Separator).		
Corrective Action:	Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P. Corrective Action Date 1/8/2021. See attached photo #2		Date: <u>01/08/2021</u>
Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs. To lock out tag out. 30 days to remove riser. Corrective Action Date 24 hrs. / 1/15/2021. See attached photo #2		Date: <u>01/15/2021</u>
Overall Good: <input type="checkbox"/>			

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	4 Strand barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berm with crude tank.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.846238,-104.339198
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
	Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 201257 Type: WELL API Number: 001-06660 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday December 4, 2020 at approximately 10:20am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at UPRR-Walker 1-29 , Renegade Oil & Gas Company LLC, at API #001-06660 in Adams County Colorado. While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Flowline risers not LO/TO or marked are considered unused equipment. Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs. To lock out tag out. 30 days to remove riser. Corrective Action Date 24 hrs. / 1/15/2021. See attached photo #2</p> <p>Dead Weeds,(next to Separator) trash and debris. Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P. Corrective Action Date 1/8/2021. See attached photo #2</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	12/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900403	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310667