

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2020

Submitted Date:

12/15/2020

Document Number:

700702029**FIELD INSPECTION FORM**

Loc ID 335481	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	----------------------------------	---	-------------------

Operator Information:
OGCC Operator Number: 10531
Name of Operator: GRIZZLY OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Status Summary:
☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
Findings:
12 Number of Comments
1 Number of Corrective Actions
☒ Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Name	Phone	Email	Comment
, Grizzly		sgshan@grizzlyenergyllc.com	SR. EH&S
Katz, Aaron		aaron.katz@state.co.us	
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295388	WELL	PR	10/27/2008	GW	045-15738	JOLLEY 31D-20-691	PR
295989	WELL	PR	04/17/2012	GW	045-15873	JOLLEY 41C-20-691	PR
295990	WELL	PR	05/09/2013	GW	045-15872	JOLLEY 41B-20-691	PR
296011	WELL	PR	10/26/2008	GW	045-15875	JOLLEY 31B-20-691	PR
296012	WELL	PR	11/09/2008	GW	045-15874	JOLLEY 41D-20-691	PR

General Comment:

COGCC Inspection Report Summary
On Tuesday 12/15/20 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Jolley 31D, at Location # 335481 in Garfield county Colorado.
While there, I observed normal production operations. All meters have been calibrated on location within the past year. Limited storm water inspection due to snow.
During this inspection the following possible compliance issues were observed:
• No evidence of tracking control BMP's
Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:	snow covered		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	chemical tank at well heads		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	YES		
--------	-----	--	--

Comment:	Two (2) braden heads are open to Atmosphere		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	295388	Type:	WELL	API Number: 045-15738 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	295989	Type:	WELL	API Number: 045-15873 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	295990	Type:	WELL	API Number: 045-15872 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	296011	Type:	WELL	API Number: 045-15875 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	296012	Type:	WELL	API Number: 045-15874 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: Limited storm water inspection due to snow.
 • No evidence of tracking control BMP's

Corrective Action: Provide proof of tracking control BMP's

Date: 01/15/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702033	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310891