

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/07/2020

Submitted Date:

12/07/2020

Document Number:

699802216

**FIELD INSPECTION FORM**

Loc ID: 312598 Inspector Name: De Paolo, Corey On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 6 Number of Comments  
 3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 53255  
 Name of Operator: MARALEX RESOURCES INC  
 Address: P O BOX 338  
 City: IGNACIO State: CO Zip: 81137

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
, BLM		jbyers@blm.gov	
, Engineering		dnr_cogccengineering@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
Graves, Jim		mrinc20@maralexinc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221992	WELL	SI	04/01/2010	GW	077-08594	SOUTH SHALE RIDGE 1-14	SI

**General Comment:**

COGCC Inspection Report Summary  
 On Monday 12/7/20 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE, Location #312598 in Mesa County Colorado.  
 Refer to document #699801878 inspection conducted on 10/2/20. Not all previous corrective actions have been completed. During this inspection the following possible compliance issues were observed: Multiple places with weeds and debris on location. See photo #1981 and #2410 with a previous corrective action date of 8/4/20. Secondary containment not adequate weeds and debris inside tank containment. See photo #1982 and #2411 with a previous corrective action date of 11/16/20. MIT required on well. With a corrective action date of 10/21/20.  
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Multiple places with weeds and debris on location. See photo #1981 and #2410		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all weeds and debris from location.		Date: 08/04/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Secondary containment not adequate weeds and debris inside tank containment. See photo #1982 and #2411			
Corrective Action:	Secondary containment structures shall be sufficiently impervious to contain discharged material. Remove weeds and repair secondary containment.			Date: 11/16/2020

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 221992 Type: WELL API Number: 077-08594 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced April 2010. Last MIT performed on 2/11/15

Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Perform MIT on well.

Date: 10/21/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
		Berms				
Ditches						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402549477	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306161">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306161</a>
699802217	Photos for Insp. #699802216	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306156</a>