

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
	Comment: iron		
Corrective Action:		Date:	

Equipment:

				corrective date
Type: Plunger Lift	# 1			
Comment:	<input style="width: 95%;" type="text"/>			
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	<input style="width: 95%;" type="text"/>			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:

Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 286141 Type: WELL API Number: 123-24137 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
This is a follow up inspection to previous inspection DOC#: 67960320. All previous corrective actions have been resolved. No new corrective actions were observed at the time of re-inspection. **Weather Conditions: cloudy, dry ground	santistb	12/16/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603551	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5311599