

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2020

Submitted Date:

12/16/2020

Document Number:

693503984**FIELD INSPECTION FORM**Loc ID 318413 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241253	WELL	PR	08/01/2017	GW	123-09041	UPRR 43 PAN AM I 21	SI

General Comment:

Location					
Lease Road:					
Type	Access				
comment:	No access road had to drive though plowed field.				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Adequate				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					
Corrective Action:					Date: _____
Good Housekeeping:					
Type	UNUSED EQUIPMENT				
Comment:	PU has not motor appears to have not been in use for an extened period of time due to bird nest in belt guard. PU, cement base, electric panel are unused equipment due to not being able to operate.				
Corrective Action:					Date:
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	PUMP JACK				
Comment:	expanded metal				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Prime Mover	# 0				
Comment:	No electric motor				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	Electric panel				
Corrective Action:					Date:
Type: Pump Jack	# 1				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 1				

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241253 Type: WELL API Number: 123-09041 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTEDComment: SI at time of inspection flow line valves are closed and PU has no motor to operate.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<u>Routine inspection.</u>	silverr	12/16/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503985	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5312195