

# Inspection Photos

API: 043-40000

Operator: JAVERNICK OIL

Inspection Date: 12/16/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-40000 | Date: 12/16/2020

## Inspection Photos



**Photo 1.** Facing southeast toward the location. The vegetation has not established at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/16/2020

## Inspection Photos



**Photo 2.** The location has not been recontoured and reclaimed..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/16/2020



## Inspection Photos



**Photo 3.** There is debris and a fence in disrepair around the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/16/2020



## Inspection Photos



**Photo 4.** There is a wood beam left at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/16/2020



## Inspection Photos



**Photo 5.** There is various remnants of debris left tat the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/16/2020



## Inspection Photos



**Photo 6.** There is cable left at the location. Also note in this picture that soils are bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/16/2020

## Inspection Photos



**Photo 7.** There is an old electric powerpole that remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/16/2020