

Inspection Photos

API: 043-40001

Operator: JAVERNICK OIL

Inspection Date: 12/16/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/16/2020

Inspection Photos



Photo 1. Facing northeast toward the location. The location has not been reclaimed and is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/16/2020

Inspection Photos



Photo 2. The southwest at the location. The location is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/16/2020

Inspection Photos



Photo 3. There is a cement block and metal pipe extending out of the ground at the northeast side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/16/2020

Inspection Photos



Photo 4. There is a metal cable and anchor that remains at the northwest side of the location next to the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/16/2020

Inspection Photos



Photo 5. There is an old power pole that remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/16/2020