

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2020

Submitted Date:

12/02/2020

Document Number:

700600223

### FIELD INSPECTION FORM

Loc ID 475565 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 34105  
Name of Operator: GILBERT-STEWART OPERATING LLC  
Address: 1801 BROADWAY STE 200  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 4 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
GILBERT, KENT	303-534-1686	kgoil@msn.com	

**General Comment:**

Inadequate berms around tank battery.

Stained soil and torn liner stored on location.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Torn liner stored on location. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/22/2021
Type	OTHER		
Comment:	Stained soil around tank battery.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.	Date:	01/22/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	Inadequate berms around tank battery. See attached photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date:

**Venting:**

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402544415	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301293">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301293</a>
700600228	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301290">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5301290</a>