

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2020

Submitted Date:

12/19/2020

Document Number:

700404650**FIELD INSPECTION FORM**Loc ID 311791 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Heil, John		john.heil@state.co.us	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232369	WELL	SI	11/01/2019	OW	103-40158	MCLAUGHLIN SR 17	SI

General Comment:

A routine inspection identified the following compliance issues:

- 1) Report past due monthly operations on Form 7. Complete by 7-15-2020.
- 2) Provide an emergency phone number that is answered. Photo 5. Complete by 12-20-2020.
- 3) Venting of gas from the open casing. Contact COGCC engineering. Photo 2.

On 12-18-2020 the emergency phone number posted on the sign, 800-209-9762 was called at 16:25, 17:20, and 20:00. No one answered and the call disconnected after 10 rings. Kris Freeman's phone number, 254-727-0435 was called at 16:25. That number is now disconnected.

This is a summary of inspection report 700404650.

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Provide an emergency phone number that is answered.](#)Corrective Action: [Install sign to comply with Rule 210.b.](#)

Date: 12/20/2020

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: Moran, Rick

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	YES		
Comment:	Gas venting out open casing. Inspector detected gas odor 20' from well. FLIR video acquired of gas venting.		
Corrective Action:	Gas being vented or flared during non-upset condition without prior approval from COGCC.	Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 232369 Type: WELL API Number: 103-40158 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations.Corrective Action: Submit required Form 7(s) to COGCC per rule 309.

Date: 07/15/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						tank

Comment: [Snow on ground.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: None Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
4:10	PM	4:15	PM	Wellhead(s)

Comment: FLIR video acquired of gas venting from open casing.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700404651	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5313777
700404652	FLIR video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5313778