

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2020

Submitted Date:

12/14/2020

Document Number:

700702024

FIELD INSPECTION FORMLoc ID 334629 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283775	WELL	PR	05/17/2006	GW	045-11993	CIRCLE B LAND 23B-35-692	PR
283989	WELL	PR	09/09/2006	GW	045-12059	CIRCLE B LAND 13C-35-692	PR
283990	WELL	PR	06/23/2006	GW	045-12064	CIRCLE B LAND 13A-35-692	PR
283992	WELL	PR	06/23/2006	GW	045-12063	CIRCLE B LAND 23D-35-692	PR
284741	WELL	PR	06/23/2006	GW	045-12259	CIRCLE B LAND 22A-35-692	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 12/14/20 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Circle B 3, at Location # 334629 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. Limited storm water inspection due to snow.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking

- No evidence of tracking control BMP's

- Signage on tank has improper labeling

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:	snow covered		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	• Signage on tank has improper labeling		
Corrective Action:	Install proper labeling	Date:	01/14/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	

Equipment:

				corrective date
Type: Bird Protectors	# 9			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 5			
Comment:	All meters have been calibrated on location within the past year.			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 5			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 5			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 5			
Comment:	Braden heads have a port for manual gauge monitoring Two (2) braden heads are tied into 100 bbl tank they are NOT open to tank at time of inspection			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	chemical tank at well heads			
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	STEEL AST		,	
Comment:	This tank is at well heads for braden heads					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: Ramsey, Scott

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	OTHER	HEATED STEEL AST		,
Comment:	250 BBL tanks and one (1) is NOT heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 283775 Type: WELL API Number: 045-11993 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 283989 Type: WELL API Number: 045-12059 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 283990 Type: WELL API Number: 045-12064 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 283992 Type: WELL API Number: 045-12063 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 284741 Type: WELL API Number: 045-12259 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
Ditches		Ditches				
Check Dams						

Comment: Limited storm water inspection due to snow.
 • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance which in turn can lead to tracking
 • No evidence of tracking control BMP's

Corrective Action: Maintain All BMP's
 Provide proof of tracking control BMP's

Date: 01/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402553767	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310066
700702027	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310063